

The main reasons for that are: – Transformers will draw a very heavy current at switch on, until the magnetic flux has stabilized. In order to mitigate the problem, a circuit for "soft-starting" the mains transformer (also known as inrush current limiter) is widely used.

